

## **Case Study: Business Aviation MRO**

Client: A large, diversified Indian business conglomerate

Aircraft Type: Embraer ERJ 135 LR

Downtime: 25 working days

Location: Hosur, near Bengaluru

### **Key Highlights:**

- Air Works performed S120 inspection and SB compliance for the client's Embraer ERJ 135, which was the first major base check by any MRO in India
- Air Works is an Embraer Authorised Service Facility for the ERJ 135 aircraft, and the contract was awarded on the basis of this accreditation
- Air Works performed a detailed S120 inspection, that included all lower checks (including S1, S3, S6, S12, S24, S60 and SBs)
- Inspection performed under DGCA approval
- Inspection performed in EASA approved Hosur facility, with direct guidance and support from the Embraer team in India